

भारत सरकार

केंद्रीय लोक निर्माण विभाग

कार्यपालक अभियंता

त्रिपुरा केंद्रीय मंडल-।

कें. लो.नि. वि. परिसर, उषाबाजार, अगरतला-०९

Email: nez2eeTcd1.cpwd@gov.in

File. No:- DB(39)/TCD-I/AGT/2021-22/ 5

CENTRAL PUBLIC WORKS DEPARTMENT OFFICE OF THE EXECUTIVE ENGINEER

TRIPURA CENTRAL DIVISION-I

C.P.W.D. Complex, Usha Bazar, Agartala-09

Ph:0381-2342238/2342205

Speed fast & Fmai

Date:07/ 0/72021



The Principal I/C Kendriya Vidyalaya, Bagafa, Santir Bazar South Tripura - 799144

Subject:- Issue of building safety certificate regarding.

Ref:- KV letter no. F-1857359/KVB/2021-22-135, dt. 26.07.2021

Sir.

As per visual inspection done by Assistant Engineer - IV and Junior Engineer on 04.08.2021, it is certified that school building is safe as on date to use provided periodical maintenance work including painting to be done. Boundary wall at some location is required to be reconstructed for approx 150 m

Major repairing including painting etc is required in almost all staff Qtrs to extend the service life of buildings.

Yours Sincerely

Executive Engineer Tripura Central Division-I CPWD, Agartala

Copy To:-

1. The Assistant Engineer, TCSD-IV/TCD-I, CPWD, Usha Bazar, Agartala Tripura - 799009 for information.

Executive Engineer